

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Structure

Page Last Modified: 03/11/2024

64. Footings (S)

Type (check all that apply):

- Concrete
- Other (specify)

64a. Evidence of structural concerns (check all that apply)

- Structural Cracks
- Heaving/Jacking
- Decay/Corrosion
- Water Penetration
- Unsupported Ends
- Other (specify)
- None

64.a1. If "Other" please specify

(No Response)

64b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

64c. Year of Last Major Reconstruction/Replacement

2020

64d. Expected Remaining Useful Life (Years):

30

64e. Cost to Reconstruct/Replace \$:

(No Response)

64f. Comments:

Footins are inaccessible.

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Structure

Page Last Modified: 03/11/2024

63. Columns (S)

Type (check all that apply):

- Concrete
- Masonry
- Steel
- Stone
- Wood
- Other (specify)
- N/A (None)

63.1. If "Other" please specify

(No Response)

63a. Evidence of structural concerns (check all that apply)

- Structural Cracks
- Heaving/Jacking
- Decay/Corrosion
- Water Penetration
- Unsupported Ends
- Other
- None

63b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

63c. Year of Last Major Reconstruction/Replacement

2020

63d. Expected Remaining Useful Life (Years):

30

63e. Cost to Reconstruct/Replace \$:

(No Response)

63f. Comments:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Structure

Page Last Modified: 03/11/2024

62a. Type (check all that apply)

- Concrete
- Masonry
- Steel
- Stone
- Wood
- Other (specify)
- N/A (none)

62a1. If "Other" please specify

(No Response)

62b. Evidence of structural concerns (check all that apply)

- Structural Cracks
- Heaving/Jacking
- Decay/Corrosion
- Water Penetration
- Unsupported Ends
- Other
- None

62c. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

62d. Year of Last Major Reconstruction/Replacement

2020

62e. Expected Remaining Useful Life (Years):

30

62f. Cost to Reconstruct/Replace \$:

(No Response)

62g. Comments:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Structure

Page Last Modified: 03/11/2024

Building Structure

61. Foundation (S)

61a. Type (check all that apply):

- Reinforced Concrete
- Masonry on Concrete Footing
- Other (specify)

61a1. If "Other" please specify

(No Response)

61b. Evidence of structural concerns (check all that apply):

- Structural Cracks
- Heaving/Jacking
- Decay/Corrosion
- Water Penetration
- Unsupported Ends
- Other
- None

61c. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

61d. Year of Last Major Reconstruction/Replacement:

2020

61e. Expected Remaining Useful Life (Years):

30

61f. Cost to Reconstruct/Replace \$:

(No Response)

61g. Comments:

(No Response)

62. Piers (S)

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Other Site Features

Page Last Modified: 03/11/2024

56b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

56c. Year of Last Major Reconstruction/Replacement:

2005

56d. Expected Remaining Useful Life (Years):

5

56e. Cost to Reconstruct/Replace \$:

25,000.00

56f. Comments:

Reconstruct asphalt sidewalk heading to main school building.

57. Playgrounds and Playground Equipment

- Yes
- No

58. Athletic Fields and Play Fields

- Yes
- No

59. Exterior Bleachers / Stadiums

- Yes
- No

60. Related Structures (such as Press Boxes, Dugouts, Climbing Walls, etc.)

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Other Site Features

Page Last Modified: 03/11/2024

SITE FEATURES

55. Pavement (Roadways and Parking Lots)

- Yes
- No

55a. Type: (check all that apply)

- Concrete
- Asphalt
- Gravel
- Other

55b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

55c. Year of Last Major Reconstruction/Replacement:

2020

55d. Expected Remaining Useful Life (Years):

10

55e. Cost to Reconstruct/Replace \$:

(No Response)

55f. Comments:

(No Response)

56. Sidewalks

- Yes
- No

56a. Type: (check all that apply)

- Asphalt
- Concrete
- Gravel
- Paver
- Other

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Site Utilities

Page Last Modified: 03/11/2024

51. Wetponds

51a. Does this facility have wetponds?

- Yes
- No

52. Manufactured Stormwater Proprietary Units

52a. Does this facility have proprietary units?

- Yes
- No

53. Point of Outfall Discharge: (check all that apply)

- Municipal storm sewer system
- Combined sewer system
- Surface Water
- On-site recharge
- Other (describe)
- Not Applicable

54. Outfall Reconnaissance Inventory

Were all stormwater outfalls inspected during dry weather for signs of non-stormwater discharge?

- Yes
- No
- Not Applicable

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Site Utilities

Page Last Modified: 03/11/2024

47e. Cost to Reconstruct/Replace \$:

(No Response)

47f. Comments:

(No Response)

48. Outfalls

48a. Does this facility have outfalls?

Yes

No

48b. Condition:

Excellent

Satisfactory

Unsatisfactory

Non-Functioning

Critical Failure

48c. Year of Last Major Reconstruction/Replacement:

1950

48d. Expected Remaining Useful Life (Years):

10

48e. Cost to Reconstruct/Replace \$:

(No Response)

48f. Comments:

(No Response)

49. Infiltration Basins/Chambers

49a. Does this facility have infiltration basins/chambers?

Yes

No

50. Retention Basins

50a. Does this facility have retention basins?

Yes

No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Site Utilities

Page Last Modified: 03/11/2024

46. Catch Basins/Drop Inlets/Manholes

46a. Does this facility have catch basins/drop inlets/manholes?

- Yes
- No

46b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

46c. Year of Last Major Reconstruction/Replacement:

1994

46d. Expected Remaining Useful Life (Years):

10

46e. Cost to Reconstruct/Replace \$:

(No Response)

46f. Comments:

(No Response)

47. Culverts

47a. Does this facility have culverts?

- Yes
- No

47b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

47c. Year of Last Major Reconstruction/Replacement:

1994

47d. Expected Remaining Useful Life (Years):

10

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Site Utilities

Page Last Modified: 03/11/2024

44b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

44c. Year of Last Major Reconstruction/Replacement:

2020

44d. Expected Remaining Useful Life (Years):

10

44e. Cost to Reconstruct/Replace \$:

(No Response)

44f. Comments:

(No Response)

45. Open Drainage Pipe Stormwater Management System

45a. Does this facility have an open stormwater system (ditch)?

- Yes
- No

45b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

45c. Year of Last Major Reconstruction/Replacement:

1994

45d. Expected Remaining Useful Life (Years):

10

45e. Cost to Reconstruct/Replace \$:

(No Response)

45f. Comments:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Site Utilities

Page Last Modified: 03/11/2024

43a. Service Provider:

- Municipal or utility provided
- Self-Generated
- Other
- N/A

43b. Type of Service:

- Above Ground
- Below Ground
- N/A

43c. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

43d. Year of Last Major Reconstruction/Replacement:

2020

43e. Expected Remaining Useful Life (Years):

30

43f. Cost to Reconstruct/Replace \$:

(No Response)

43g. Comments:

Fed from Main Building.

SITE FEATURES

44. Closed Drainage Pipe Stormwater Management System

44a. Does this facility have a closed pipe system?

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Site Utilities

Page Last Modified: 03/11/2024

41e. Cost to Reconstruct/Replace \$:

(No Response)

41f. Comments:

(No Response)

42. Site Fuel Oil

Yes

No

42a. Number of Above-Ground Tanks:

1

42a.1 Capacity of Above-Ground Tanks (gallons):

3,000

42b. Number of Below-Ground Tanks:

0

42b.1 Capacity of Below-Ground Tanks (gallons):

0

42c. Condition:

Excellent

Satisfactory

Unsatisfactory

Non-Functioning

Critical Failure

N/A

42d. Year of Last Major Reconstruction/Replacement:

2005

42e. Expected Remaining Useful Life (Years):

15

42f. Cost to Reconstruct/Replace \$:

(No Response)

42g. Comments:

(No Response)

43. Site Electrical, Including Exterior Distribution

Yes

No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Site Utilities

Page Last Modified: 03/11/2024

40a. Type of Service:

- Municipal or utility sewer
- Site septic
- Other

40b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

40c. Year of Last Major Reconstruction/Replacement:

2004

40d. Expected Remaining Useful Life (Years):

10

40e. Cost to reconstruct/Replace \$:

(No Response)

40f. Comments:

(No Response)

41. Site Gas

- Yes
- No

41a. Type of gas service:

- Natural Gas
- Liquid Petroleum

41b. Condition:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

41c. Year of Last Major Reconstruction/Replacement;

2004

41d. Expected Remaining Useful Life (Years):

15

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Site Utilities

Page Last Modified: 03/11/2024

SITE UTILITIES

39. Water (H)

- Yes
- No

39a. Type of Service:

- Municipal or Utility provided
- Well
- Other

39b. Types of water service piping

- Iron
- Galvanized
- Copper
- Lead
- PVC
- Other
- N/A (None)

39c. Overall condition of water service piping

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

39d. Year of Last Major Reconstruction/Replacement:

2004

39e. Expected Remaining Useful Life (Years):

10

39f. Cost to Reconstruct/Replace \$:

(No Response)

39g. Comments:

(No Response)

40. Site Sanitary (H)

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Program Spaces

Page Last Modified: 03/04/2024

Program Spaces

35. Number of instructional classrooms:

0

36. Gross square footage of all instructional classrooms (combined):

0.00

37. Other spaces provided:

- a. N/A (none)
- b. Administration
- c. Art
- d. Audio Visual
- e. Auditorium
- f. Cafeteria
- g. Computer Room
- h. Guidance
- i. Gymnasium
- j. Health Office
- k. Home & Careers
- l. Kitchen
- m. Large Group Instruction
- n. Library
- o. Multipurpose Rooms
- p. Music
- q. Pre-K
- r. Remedial Rooms
- s. Resource Rooms
- t. Science Labs
- u. Special Education
- v. Swimming Pool
- w. Teacher Resource
- x. Technology/Shop
- y. Other (please describe)

37a. Describe other spaces

Bus Garage

Space Adequacy

38. Rating of space adequacy:

- Good
- Fair
- Poor

38a. Enter comments:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Information

Page Last Modified: 03/11/2024

32. Grades Housed

<input type="checkbox"/> Pre-K	<input type="checkbox"/> 7th
<input type="checkbox"/> Kindergarten	<input type="checkbox"/> 8th
<input type="checkbox"/> 1st	<input type="checkbox"/> 9th
<input type="checkbox"/> 2nd	<input type="checkbox"/> 10th
<input type="checkbox"/> 3rd	<input type="checkbox"/> 11th
<input type="checkbox"/> 4th	<input type="checkbox"/> 12th
<input type="checkbox"/> 5th	<input checked="" type="checkbox"/> N/A (none)
<input type="checkbox"/> 6th	

33. For how many instructional days during the school year prior to the BCS assigned year (July 1 through June 30) was the building closed due to facilities failures, system malfunctions, structural problems, fire, etc? (if none, enter "0")

0

34. Is the building used for instructional purposes in the summer?

Yes
 No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Information

Page Last Modified: 03/11/2024

28. For which of the following purposes is the building currently used? (check all that apply)

- Used for student instructional purposes
- Used for district administration
- Used for other district purposes
- Used by other organization(s)

28a. Describe use for other district purposes:

Bus maintenance

Building Users

29. How many students were registered to receive instruction in this building as of the last year? (If none, enter "0") and skip to "Program Spaces" section. (Do not include evening class students)

0

30. Of these registered students, how many receive most of their instruction in:

	Quantity
Permanent instructional spaces (i.e., regular classrooms)	0
Temporary instructional spaces (i.e., portable or demountable classrooms) attached to the building	0
Non-instructional spaces used as instructional spaces	0

31. If the answer is greater than zero, which types of non-instructional spaces were being used for instructional purposes on October 1, 2019? (check all that apply)

- Cafeteria
- Gymnasium
- Administrative Spaces
- Library
- Lobby
- Stairwell
- Storage space
- Other (please describe)
- None

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Information

Page Last Modified: 03/11/2024

	Year
Addition #7	(No Response)
Addition #8	(No Response)
Addition #9	(No Response)

23. Square feet of construction

	Sq Feet
Original construction	20,020.00
Addition #1	(No Response)
Addition #2	(No Response)
Addition #3	(No Response)
Addition #4	(No Response)
Addition #5	(No Response)
Addition #6	(No Response)
Addition #7	(No Response)
Addition #8	(No Response)
Addition #9	(No Response)

24. Gross square ft. of Building as currently configured:

20,020

25. Number of Floors:

1

26. How many full-time and part-time custodians are employed at the school (or work in the building)?

	Count Employees
Full-time custodians:	0
Part-time custodians:	0
Totals:	0

Building Ownership and Occupancy Status

27. Building Ownership (check one):

- Owned and used by district
- Owned by District and leased to non-district entity
- Owned by District, part used by district, part leased to non-district entity
- Owned by non-district entity and leased to district

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Information

Page Last Modified: 03/11/2024

13. Estimated capital construction expenses anticipated for this building through the 2024 calendar year excluding maintenance (to be answered after the building inspection is complete)

0.00

14. Overall building rating (to be answered after the building inspection is complete)

- Excellent
- Satisfactory
- Unsatisfactory
- Failing

15. Was overall building rating established after consultation with health and safety committee in accordance with Commissioner's Regulations 155.4(c)(1)?

- Yes
- No

16. A/E Firm Name:

LABELLA ASSOCIATES

17. A/E Firm Address:

300 STATE STREET-SUITE 201, ROCHESTER NY 14614

18. A/E Firm Phone Number:

7162419276

19. E-mail:

BDERISZNER@LABELLAPC.COM

20. A/E Name:

BRENT DERISZNER

21. A/E License #:

042962

Building Age, Gross Square Footage and Maintenance Staff

22. Building Age

	Year
Original Construction	2020
Addition #1	(No Response)
Addition #2	(No Response)
Addition #3	(No Response)
Addition #4	(No Response)
Addition #5	(No Response)
Addition #6	(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Information

Page Last Modified: 03/11/2024

Building Information

1. Name of school district

DUNDEE CENTRAL SCHOOL

2. SED District 8-Digit BEDS Code

68080104

3. Building Name:

BUS GARAGE

4. SED 4-Digit Facility Code:

4002

5. Survey Inspection Date:

07/17/2023

6. Building 911 Address:

55 WATER STREET

7. City:

DUNDEE

8. Zip Code:

14837

9. Certificate of Occupancy Status:

- A - Annual
- T - Temporary
- N - None

10. Certificate of Occupancy Expiration Date:

05/01/2024

10a. Is this a manufactured building? (Relocatable, modular, portable)

- Yes
- No

11. Have there been renovations or construction in the building during the past 12 months?

- Yes
- No

12. Was major construction/renovation work since 2015 conducted when school was in session?

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Structure

Page Last Modified: 03/11/2024

65. Structural Floors (S)

65a. Type (check all that apply):

- Concrete Deck on Wood Structure
- Concrete/Metal Deck/Metal Joists
- Cast in Place Concrete Structural System
- Precast Concrete Structural System
- Reinforced Concrete Slab on Grade
- Wood Deck on Wood Trusses
- Wood Deck on Wood Joists
- Other (specify)

65b. Evidence of Structural Concerns with Floor Support System (Beams/Joists/Trusses, etc.) (check all that apply):

- Structural Cracks
- Unsupported Ends
- Rot/Decay/Corrosion
- Deflection
- Seriously Damaged/Missing Components
- Other Problems
- None

65b.1 Describe Other Problems:

(No Response)

65c. Evidence of Structural Concerns with Structural Floor Deck (check all that apply):

- Cracks
- Deflection
- Rot/Decay/Corrosion
- None

65d. Overall Condition of Structural Floors:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

65e. Year of Last Major Reconstruction/Replacement:

2020

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Structure

Page Last Modified: 03/11/2024

65f. Expected Remaining Useful Life (Years):

30

65g. Cost to Reconstruct/Replace \$:

(No Response)

65h. Comments:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Envelope

Page Last Modified: 03/11/2024

BUILDING ENVELOPE

66. Exterior Walls/Columns (S)

66a. Material (check all that apply):

- Aluminum/Glass Curtain Wall
- Brick
- Concrete
- Composite Insulated Panels
- Masonry
- Steel
- Wood
- Other (specify)

66b. Evidence of Structural Concerns with Support System (columns, base plates, connections, etc.)

(check all that apply):

- Structural Cracks
- Rot/Decay/Corrosion
- Other Problems
- None

66b.1 Describe Other Problems:

(No Response)

66c. Evidence of Concerns with Exterior Cladding (check all that apply):

- Cracks/Gaps
- Inadequate Flashing
- Efflorescence
- Moisture Penetration
- Rot/Decay/Corrosion
- Other Problems
- None

66c.1 Describe Other Problems:

(No Response)

66d. Overall Condition of Exterior Walls/Columns:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Envelope

Page Last Modified: 03/11/2024

66e. Year of Last Major Reconstruction/Replacement:

2020

66f. Expected Remaining Useful Life (Years):

30

66g. Cost to Reconstruct/Replace \$:

(No Response)

66h. Comments:

(No Response)

67. Chimneys (S)

Yes

No

68. Parapets (S)

Yes

No

69. Exterior Doors

69a. Overall Condition of Exterior Door Units:

Excellent

Satisfactory

Unsatisfactory

Non-Functioning

Critical Failure

69b. Do any exterior doors have magnetic locking devices?

Yes

No

69c. Safety/Security features are adequate?

Yes

No

69d. Year of Last Major Reconstruction/Replacement:

2020

69e. Expected Remaining Useful Life (Years):

20

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Envelope

Page Last Modified: 03/11/2024

69f. Cost to Reconstruct/Replace \$:

(No Response)

69g. Comments:

(No Response)

70. Exterior Steps, Stairs, Ramps (S)

Yes

No

71. Fire Escapes (S)

71a. Does This Facility Have One or More Fire Escapes?

Yes

No

72. Windows

Yes

No

72a. Window Material: (check all that apply)

Aluminum

Steel

Vinyl

Solid Wood

Wood w/ External Cladding System

Other

72a1. If "Other" please specify

(No Response)

72b. Overall Condition of Windows:

Excellent

Satisfactory

Unsatisfactory

Non-Functioning

Critical Failure

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Envelope

Page Last Modified: 03/11/2024

72c. All Rescue Windows are Operable:

- Yes
- No
- N/A

72d. Year of Last Major Reconstruction/Replacement:

2020

72e. Expected Remaining Useful Life (Years):

20

72f. Cost to Reconstruct/Replace \$:

(No Response)

72g. Comments:

(No Response)

73. Roof and Skylights (S)

- Yes
- No

73a. Type of roof construction (check all that apply):

- Concrete on metal deck on metal trusses/joists
- Concrete (poured or plank) on concrete beams
- Gypsum (poured or plank) on metal trusses/joists
- Metal deck on metal trusses/joists
- Wood deck on wood trusses/joists
- Wood deck on metal trusses/joists
- Tectum on metal trusses/joists
- Other (describe below)

73a.1 Other roof construction type:

(No Response)

73b. Type of roofing material (check all that apply):

- Single-ply membrane
- Built-up
- Asphalt shingle
- Pre-formed metal
- IRMA
- Slate
- Fluid applied seamless surfacing
- Other (describe below)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Envelope

Page Last Modified: 03/11/2024

73b.1 Other roofing material:

(No Response)

73c. Evidence of structural concerns with roof support system (beams/joists/trusses, etc.) (check all that apply):

- Structural cracks
- Unsupported ends
- Rot/Decay/Corrosion
- Deflection
- Seriously damaged/missing components
- Other concerns (describe)
- None

73c.1 Describe other concerns:

(No Response)

73d. Evidence of structural concerns with roof deck (check all that apply):

- Cracks
- Deflection
- Rot/Decay/Corrosion
- None

73e. Does this facility have skylights?

- Yes
- No

73f. Skylight material (check all that apply):

- Plastic
- Glass
- Other
- N/A

73g. Overall condition of skylights:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Envelope

Page Last Modified: 03/11/2024

73h. Evidence of concerns with roofing, skylights, flashings, and drains (check all that apply):

- Failures/Splits/Cracks
- Rot/Decay/Corrosion
- Inadequate flashing/curbs/pitch pockets
- Inadequate or poorly functioning roof drains
- Evidence of water penetration/active leaks
- Other (specify)
- None

73h.1 Specify other concerns:

(No Response)

73i. Overall Condition of Roof and Skylights:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

73j. Year of Last Major Reconstruction/Replacement:

2020

73k. Expected Remaining Useful Life (Years):

20

73l. Cost to Reconstruct/Replace \$:

(No Response)

73m. Comments:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Interiors

Page Last Modified: 03/11/2024

BUILDING INTERIOR

74. Interior Bearing Walls and Fire Walls (S)

- Yes
- No

74a. Overall condition of interior bearing walls and fire walls:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-functioning
- Critical Failure

74b. Year of Last Major Reconstruction/Replacement:

2020

74c. Expected Remaining Useful Life (Years):

30

74d. Cost to Reconstruct/Replace \$:

(No Response)

74e. Comments:

(No Response)

74.f Regulatory

Have design professionals provided inventory of construction regulated under BCNYS Ch7, including assessment of their condition and maintenance, as required by NYSFC Ch7 and NYSPMC 703? This includes, but is not limited to:

[check each item provided to the district]

- Fire-resistance rated assemblies;
- Smoke barriers and smoke partitions;
- Penetrations, joints, voids, door
- Assessment of Ch7 regulated assembly either damaged, altered, breached, or penetrated;
- Confirmation of compliant repair or protection of Ch7 regulated assembly either damaged, altered, breached, or penetrated;
- Other:

74.f Other:

(No Response)

75. Other Interior Walls

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Interiors

Page Last Modified: 03/11/2024

75a. Overall condition of other interior walls:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

75b. Year of Last Major Reconstruction/Replacement:

2020

75c. Expected Remaining Useful Life (Years):

30

75d. Cost to Reconstruct/Replace \$:

(No Response)

75e. Comments:

(No Response)

76. Carpet

- Yes
- No

77. Resilient Tiles or Sheet Flooring

- Yes
- No

78. Hard Flooring (concrete; ceramic tile; stone; etc)

- Yes
- No

78a. Where located (check all that apply):

- Classrooms
- Corridors
- Offices
- Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- Kitchen
- Locker Rooms/Toilet Rooms
- Other Areas

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Interiors

Page Last Modified: 03/11/2024

78b. Overall condition of hard flooring:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

78c. Year of Last Major Reconstruction/Replacement:

2020

78d. Expected Remaining Useful Life (Years):

15

78e. Cost to Reconstruct/Replace \$:

(No Response)

78f. Comments:

(No Response)

79. Wood Flooring

- Yes
- No

80. Ceilings (H)

- Yes
- No

80a. Overall condition of ceilings:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

80b. Year of Last Major Reconstruction/Replacement:

2020

80c. Expected Remaining Useful Life (Years):

15

80d. Cost to Reconstruct/Replace \$:

(No Response)

80e. Comments:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Interiors

Page Last Modified: 03/11/2024

81. Lockers

- Yes
- No

81d. Cost to Reconstruct/Replace \$:

(No Response)

82. Interior Doors

- Yes
- No

82a. Overall condition of interior door units:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

82b. Overall condition of interior door hardware:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

82c. Year of Last Major Reconstruction/Replacement:

2020

82d. Expected Remaining Useful Life (Years):

20

82e. Cost to Reconstruct/Replace \$:

(No Response)

82f. Comments:

(No Response)

83. Interior Stairs (H)

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Building Interiors

Page Last Modified: 03/11/2024

84. Elevator, Lift, and Escalators (H)

- Yes
- No

85. Swimming Pool and Swimming Pool Systems (H)

- Yes
- No

86. Interior Bleachers

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

HVAC Systems

Page Last Modified: 03/11/2024

HVAC Systems

87. Heat Generating Systems (H)

- Yes
- No

87a. Heat generation source (check all that apply):

- Biomass
- Boiler / Hot Water
- Boiler / Steam
- Cogeneration Plant
- Electric
- Furnace / Forced Air
- Geothermal
- Heat Pump
- Unit Ventilation
- Other (describe below)

87a.1 Other heat generation source:

Overhead radiant heaters.

87b. Overall condition of heat generating systems:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

87c. Year of Last Major Reconstruction/Replacement:

2020

87d. Expected Remaining Useful Life (Years):

20

87e. Cost to Reconstruct/Replace \$:

75,000.00

87f. Comments:

(No Response)

88. Ventilation System (exhaust fans, etc) (H)

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

HVAC Systems

Page Last Modified: 03/11/2024

88a. Type of ventilation system (check all that apply)

<input type="checkbox"/> Natural ventilation	<input type="checkbox"/> Heat pump
<input type="checkbox"/> Central system	<input type="checkbox"/> Split system/ variable refrigerant
<input checked="" type="checkbox"/> Energy recovery ventilator	<input checked="" type="checkbox"/> Powered relief air system
<input checked="" type="checkbox"/> Rooftop units	<input type="checkbox"/> Gravity/barometric relief
<input checked="" type="checkbox"/> Unitary (UVs, FC/BC, PTAC)	<input type="checkbox"/> Other (specify)
<input type="checkbox"/> Forced air furnace	

88b. If "Other" please specify here

(No Response)

88c. Overall condition of ventilation systems

Excellent

Satisfactory

Unsatisfactory

Non-functioning

Critical Failure

88d. Year of last major reconstruction/replacement

2020

88e. Expected remaining useful life (years):

15

88f. Cost to reconstruct/replace \$:

(No Response)

88g. Comments

(No Response)

89. Mechanical Cooling / Air-Conditioning Systems

Yes

No

89a. Types of mechanical cooling

Chiller/chilled water

Geothermal

Air cooled

Water cooled

DX/Split system

Heat pump

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

HVAC Systems

Page Last Modified: 03/11/2024

89b. Overall condition of cooling/air-conditioning systems:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

89c. Year of Last Major Reconstruction/Replacement:

2020

89d. Expected Remaining Useful Life (Years):

12

89e. Cost to Reconstruct/Replace \$:

45,000.00

89f. Comments:

(No Response)

90. Piped Heating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convectors, Traps, Insulation, etc. (H)

- Yes
- No

90a. Overall condition of piped heating and cooling distribution systems:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

90b. Year of Last Major Reconstruction/Replacement:

2020

90c. Expected Remaining Useful Life (Years):

30

90d. Cost to Reconstruct/Replace \$:

(No Response)

90e. Comments:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

HVAC Systems

Page Last Modified: 03/11/2024

91. Ducted Heating and Cooling Distribution Systems: Ductwork, Control Dampers, Fire/Smoke Dampers, VAVs, Insulation, etc. (H)

- Yes
- No

91a. Overall condition of ducted heating and cooling distribution systems:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

91b. Year of Last Major Reconstruction/Replacement:

2020

91c. Expected Remaining Useful Life (Years):

20

91d. Cost to Reconstruct/Replace \$:

(No Response)

91e. Comments:

(No Response)

92. HVAC Control Systems (H)

- Yes
- No

92a. Type of control system

- Pneumatic
- Electric
- Digital Direct Control (DDC)
- Web based DDC

92b. Overall condition of control systems:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

92c. Year of Last Major Reconstruction/Replacement:

2020

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

HVAC Systems

Page Last Modified: 03/11/2024

92d. Expected Remaining Useful Life (Years):

10

92e. Cost to Reconstruct/Replace \$:

250,000.00

92f. Comments:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Plumbing Systems

Page Last Modified: 03/11/2024

PLUMBING

93. Water Supply System (H)

- Yes
- No

93a. Types of pipes (check all that apply):

- Asbestos/transite
- Copper
- Galvanized
- Iron
- Lead
- PVC/CPVC/PEX/Plastic
- Other (specify)

93b. If "Other" please specify here

(No Response)

93c. Overall condition of water supply system:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

93d. Year of Last Major Reconstruction/Replacement:

2020

93e. Expected Remaining Useful Life (Years):

50

93f. Cost to Reconstruct/Replace \$:

(No Response)

93g. Comments:

(No Response)

94. Sanitary System (H)

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Plumbing Systems

Page Last Modified: 03/11/2024

94a. Types of pipes (check all that apply):

- Iron
- Galvanized
- Copper
- Glass/ceramic
- PVC/CPVC/ABS/poly propylene/plastic
- Lead
- Other (specify)

94a1. If "Other" please specify

(No Response)

94b. Types of special sanitary systems (Check all that apply)

- Acid waste and vent
- Grease interceptor
- Oil separator
- Pumping station
- Sediment trap
- Septic tank
- Waste water treatment plant

94c. Overall condition of sanitary system:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

94d. Year of Last Major Reconstruction/Replacement:

2020

94e. Expected Remaining Useful Life (Years):

50

94f. Cost to Reconstruct/Replace \$:

(No Response)

94g. Comments:

(No Response)

95. Storm Water Drainage System (H)

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Plumbing Systems

Page Last Modified: 03/11/2024

95a. Types of pipes (check all that apply)

- Iron
- Galvanized
- Copper
- Lead
- Plastic
- Other

95a1. If "Other" please specify

(No Response)

95b. Overall condition of storm water drainage system

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

95c. Year of Last Major Reconstruction/Replacement

2020

95d. Expected Remaining Useful Life (Years)

50

95e. Cost to Reconstruct/Replace \$:

(No Response)

95f. Comments:

(No Response)

96. Hot Water Heaters (H)

- Yes
- No

96a. Type of fuel (check all that apply):

- Oil
- Natural Gas
- Electricity
- Propane
- Other (specify)

96b. If "Other" please specify

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Plumbing Systems

Page Last Modified: 03/11/2024

96c. Overall condition of hot water heaters:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

96d. Year of Last Major Reconstruction/Replacement:

2020

96e. Expected Remaining Useful Life (Years):

10

96f. Cost to Reconstruct/Replace \$:

(No Response)

96g. Comments:

(No Response)

97. Plumbing Fixtures (H)

- Yes
- No

97a. Overall condition of plumbing fixtures (including toilets, urinals, lavatories, sinks, showers, etc):

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

97b. Year of Last Major Reconstruction/Replacement:

2020

97c. Expected Remaining Useful Life (Years):

25

97d. Cost to Reconstruct/Replace \$:

(No Response)

97e. Comments:

(No Response)

98. Water Outlets/Taps for Drinking/Cooking Purposes (H)

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Plumbing Systems

Page Last Modified: 03/11/2024

98a. Overall condition of water outlets/taps (drinking fountains, bubblers, bottle fillers, kitchen prep, ice machines, etc).

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

98b. Year of last major reconstruction/replacement:

2020

98c. Expected remaining useful life (years):

15

98d. Cost to reconstruct/replace \$:

(No Response)

98e. Comments

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Fire Suppression Systems

Page Last Modified: 03/11/2024

Fire Suppression Systems

99. Fire Suppression System (H)

- Yes
- No

100. Kitchen Hoods (H)

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Electrical Systems

Page Last Modified: 03/11/2024

ELECTRICAL SYSTEMS

101. Electrical Power Distribution System (H)

Yes

No

101a. Electrical supply meets current needs:

Yes

No

101b. Condition of electrical power distribution system:

Excellent

Satisfactory

Unsatisfactory

Non-Functioning

Critical Failure

101c. Year of last major reconstruction/replacement?

2020

101d. Expected remaining useful life (years):

30

101e. Cost to reconstruct/replace:

(No Response)

101f. Comments:

(No Response)

102. Lighting Fixtures (H)

Yes

No

102a. Condition of lighting figures:

Excellent

Satisfactory

Unsatisfactory

Non-functioning

Critical failure

102b. Year of last major reconstruction/replacement:

2020

102c. Expected remaining useful life (years):

20

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Electrical Systems

Page Last Modified: 03/11/2024

102d. Cost to reconstruct/replace:

(No Response)

102e. Comments

(No Response)

103. Emergency/ Exit Lighting Systems (H):

Yes

No

103a. Overall condition of emergency/exit lighting systems:

Excellent

Satisfactory

Unsatisfactory

Non-functioning

Critical failure

103b. Year of last major reconstruction/replacement:

2020

103c. Expected remaining useful life (years):

15

103d. Cost to reconstruct/replace:

(No Response)

103e. Comments

(No Response)

104. Emergency or standby power system (H)

Yes

No

105. Fire Alarm Systems (manual, automatic fire detection, and notification appliances) (H)

Yes

No

105a. Overall condition of fire alarm system:

Excellent

Satisfactory

Unsatisfactory

Non-functioning

Critical failure

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Electrical Systems

Page Last Modified: 03/11/2024

105b. Year of last major reconstruction/replacement:

2020

105c. Expected remaining useful life (years):

25

105d. Cost to reconstruct/replace:

1,500

105e. Comments

Add heat detector to Room 107.

106. Carbon Monoxide Alarm System (H)

Yes

No

106a. Type of alarm system:

- 10-year battery stand alone alarm
- hardwired/interconnected detection and alarm
- gas detection (eg NG/CO)
- Other (specify)

106b. If "Other" please specify

(No Response)

106c. Overall condition of carbon monoxide alarm system:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-functioning
- Critical failure

106d. Year of last major reconstruction/replacement:

2020

106e. Expected remaining useful life (years):

20

106f. Cost to reconstruct/replace:

(No Response)

106g. Comments

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Electrical Systems

Page Last Modified: 03/11/2024

107. Communication Systems (H)

- Yes
- No

107a. Type of communication system (check all that apply)

- Public Address
- Phones (VOIP)
- Phones (Cellular)
- Phones (other)
- Mass Notification
- Emergency voice communication fire alarm system
- Lockdown notification system
- Other (eg. radio) (describe below)

107b. If "Other" please describe

(No Response)

107c. Communication systems are adequate:

- Yes
- No

107d. Condition of communication system:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-functioning
- Critical failure

107e. Year of last major reconstruction/replacement:

2020

107f. Expected remaining useful life:

20

107g. Cost to replace/reconstruct:

(No Response)

107h. Comments

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Student Transportation Facilities

Page Last Modified: 03/11/2024

Student Transportation Facilities

108. Is this building a transportation facility

- Yes
- No

108a. Type of transportation facility

- Bus/vehicle maintenance facility
- Bus storage facility

109. Does this facility have a fuel dispensing system?

- Yes
- No

109a. Overall condition of fuel dispensing system

- Excellent
- Satisfactory
- Unsatisfactory
- Non-functioning
- Critical failure
- N/A

109b. Year of last major reconstruction/replacement

2023

109c. Expected remaining useful life (years):

20

109d. Cost to reconstruct/replace:

(No Response)

109e. Comments

(No Response)

110. Does this facility have vehicle lifts

- Yes
- No

111. Does this facility have a bus wash system?

- Yes
- No

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Student Transportation Facilities

Page Last Modified: 03/11/2024

111a. Overall condition of bus wash

- Excellent
- Satisfactory
- Unsatisfactory
- Non-funtioning
- Critical failure
- N/A

111b. Year of last major reconstruction/replacement

2020

111c. Expected remaining useful life (years):

20

111d. Cost to reconstruct/replace:

(No Response)

111e. Comments

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Accessibility

Page Last Modified: 03/11/2024

ACCESSIBILITY

112. Exterior Accessible Route to Building (H)

People with disabilities should be able to arrive on site, approach the building, and enter as freely as everyone else. At least one route of travel should be safe and accessible for everyone, including people with disabilities. This route must include handicapped parking, curb cuts, ramps, and automatic door operators as necessary to enter the building.

Is there an accessible exterior route as specified above?

- Yes
- No

112a. Features provided for exterior accessible route (check all that apply)

- Curb ramps
- Exterior ramps
- Handicap parking

112b. Cost of improvements needed to provide exterior accessible route to building \$:

(No Response)

112c. Comment

(No Response)

113. Is there an exterior accessible route to recreational facilities?

- Yes
- No

113a. Cost of improvements to provide exterior accessible route(s) to recreational facilities \$:

(No Response)

113b. Comments

(No Response)

114. Exterior recreational facilities that are on an accessible route and meet accessibility standards (check all that apply)

- Playground and play equipment
- Playfield(s)
- Athletic Field(s)
- Exterior Bleachers
- Bathroom Facilities
- Concession Stand

114a. Cost of improvements to provide exterior accessible recreational facilities \$:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Accessibility

Page Last Modified: 03/11/2024

114b. Comments

(No Response)

115. Interior Accessible Route, Access to Goods and Services, and Restroom Facilities (H)

The layout of the building should allow people with disabilities to obtain materials or services and use the facilities without assistance. This should include access to general purpose and specialized classrooms, public assembly spaces (such as libraries, gymnasiums, auditoriums), nurse's office, main office, and restroom facilities. Services include drinking fountains, telephones, and other amenities.

Is there an interior accessible interior route as specified above?

Yes

No

115a. Cost of improvements needed to provide interior accessible route(s) as spcified above \$:

(No Response)

115b. Comments

(No Response)

116. Does this facility have interior spaces that meet accessibility standards (check all that apply)

- Classrooms
- Labs (science, art, technology, etc)
- Shops
- Main Office
- Health Office
- Gymnasium
- Cafeteria
- Auditorium
- Stage
- Restrooms on each floor

116a. Cost of improvements to provide interior spaces that meet accessibility standards \$:

(No Response)

116b. Comments

This facility is a Bus Garage and does not have any of the spaces listed above. It does have storage rooms, an office, and a break room that are accessible.

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Environment/Comfort/Health

Page Last Modified: 03/11/2024

ENVIRONMENT/COMFORT/HEALTH

117. General Appearance

117a. Overall Rating:

- Good
- Fair
- Poor

117b. Comments:

(No Response)

118. Cleanliness (H)

118a. Overall Rating:

- Good
- Fair
- Poor

118b. Comments:

(No Response)

119. Are there walk off mats; grills in the entryway?

- Yes
- No

120. Is there noise in classrooms from HVAC units, traffic, etc. that may impact education? (H)

- Yes
- No

121. Lighting Quality (H):

121a. Types of lighting in general purpose classrooms (check all that apply):

- Daylight (natural)
- Not full spectrum
- Full spectrum
- LED
- Flourescent
- Other (describe)

121a.1 Describe Other:

There are no instructional spaces. This is a bus garage.

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Environment/Comfort/Health

Page Last Modified: 03/11/2024

121b. Are there blinds in the classroom to prevent glare?

- Yes
- No

121c. Overall Rating:

- Good
- Fair
- Poor

121d. Comments:

(No Response)

122. Evidence of Vermin (H)

122a. Is there evidence of active infestations of...(check all that apply)?

- Rodents
- Wood-boring or Wood-eating Insects
- Cockroaches
- Other Vermin
- None

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Indoor Air Quality

Page Last Modified: 03/11/2024

Indoor Air Quality

123. Mold (H)

123a. Is there visible mold or moldy odors?

- Yes
- No

123b. Are any surfaces constructed of any of the following materials?

- Paper-faced or gypsum products
- Cellulose products (typically ceiling tiles)
- Not Applicable

123c. Is there evidence of water intrusion?

- Yes
- No

123d. Estimated cost of necessary improvements \$:

(No Response)

123e. Comments:

(No Response)

124. Humidity/Moisture (H)

124a. Overall rating of humidity/moisture condition in building:

- Good
- Fair
- Poor

124b. Are any of the following found in/or around classroom areas (check all that apply)?

- Active leaks in roof
- Active leaks in plumbing
- Moisture condensation
- Visible stains or water damage
- None

124c. Are any of the following found in/or around other areas (check all that apply)?

- Active leaks in roof
- Active leaks in plumbing
- Moisture condensation
- Visible stains or water damage
- None

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Indoor Air Quality

Page Last Modified: 03/11/2024

125. Ventilation: fresh air intake locations, air filters, etc. (H)

125a. Are fresh air intakes near the bus loading, truck delivery, or garbage storage/disposal areas?

- Yes
- No

125b. Is there accumulated dirt, dust or debris around fresh air intakes?

- Yes
- No

125c. Are fresh air intakes free of blockage?

- Yes
- No

125d. Is accumulated dirt, dust or debris in ductwork?

- Yes
- No

125e. Are dampers functioning as designed?

- Yes
- No

125f. Condition of air filters:

- Good
- Fair
- Poor

125g. Outside air is adequate for occupant load:

- Yes
- No

125h. Rating of ventilation/indoor air quality:

- Good
- Fair
- Poor

125i. Comments:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Indoor Air Quality

Page Last Modified: 03/11/2024

126. Indoor Air Quality (IAQ) Plan (H)

126a. Does the school district use EPA's *Tools for Schools* program?

- Yes
- No

126b. If No, is some other IAQ management plan used?

- Yes
- No

126c. Has the District assigned IAQ responsibilities to a designated individual?

- Yes
- No

126c.1 If Yes, what is their job title?

Facilities Director

127. Does the school practice Integrated Pest Management (IPM)? (H)

- Yes
- No

127a. Is vegetation kept one foot away from the building?

- Yes
- No

127b. Are crevices and holes in walls, floors and pavement sealed or eliminated?

- Yes
- No

127c. Is there a certified pesticide applicator on staff?

- Yes
- No

127d. Are pesticides used in the building?

- Yes
- No

127d.1 If Yes, how are they typically applied?

- Spot treatment
- Area wide treatments

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Indoor Air Quality

Page Last Modified: 03/11/2024

127e. Are pesticides used on the grounds?

- Yes
- No

127e.1 If Yes, was an emergency exemption granted by the Board of Education?

- Yes
- No

128. Does the school have a passive radon mitigation system installed (was built with radon resistant features)?

(H)

- Yes
- No

128a. Has the facility been tested for the presence of radon?

- Yes
- No

128b. Were any of the results of the test greater than or equal to 4 picocuries per liter (pCi/L)?

- Yes
- No

128c. If Yes, did the school take steps to mitigate the elevated radon levels?

- Yes, active mitigation system installed
- Yes, passive mitigation system made active
- Yes, ventilation controls (HVAC) adjusted
- Yes, other (describe)
- No action taken

128c.1 Describe other actions taken to mitigate elevated radon levels:

(No Response)

2023 BUILDING CONDITION SURVEY - 2023 - DCS BCS 2023-BUS

Emergency Shelter

Page Last Modified: 03/11/2024

Emergency Shelter

129. Does this building serve as an emergency shelter?

Yes

No

